



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/11011ME-1045/1

Work Order Type: Weatherization

Audit Name: 11011ME-1045

CLIENT INFORMATION

Client Name:

Address:

Client ID: 11011ME-1045

LENIOR CITY, TN

Alt. Client ID:

AGENCY INFORMATION

Agency: Mid-East Community Action Agency

Agency Phone: (865) 354-0450

Address: P. O. Box 790

Fax:

Kingston, TN 37763

Email Address: mecaawap@mecaa.net

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

MOBLE HOME
AUDITOR SCOFIELD
ELE HEAT

Client Name:

Client ID: 11011ME-1045

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/11011ME-1045/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 6

Measures

Measure 1 COOL SEAL ROOF 720 SQFT

Components

Inspected

Comment COOLSEAL ROOF 2 COATS WHITE 720 SQFT (REF:TWFG-PG-279-280)

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	COOLSEAL	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 REPLACE BROKEN GLASS ON WINDOW

Components C1

Inspected

Comment REPAIR BROKEN GLASS APPROX 27"X13" WINDOW C ON BACK OF HOUSE

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	BROKEN GLASS	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 11011ME-1045

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/11011ME-1045/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 6

Measure 3 REPLACE DOOR B**Components****Inspected****Comment** REPLACE SWING OUT DOOR "B" 32"X72"☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Doors	MOBLE HOME DOOR SWINGOUT	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 4 General Air Sealing****Components****Inspected****Comment** MASTIC 6 BOOTS AND 1 RETURN☐CHECK DUCT UNDER HOUSE THAT CONNECTS TO OUTSIDE A/C UNIT L
BOOTS READ 13 OR HIGHER ON BLOWER TEST(REF-PG-247 & 264-266)

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	General air sealing	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 11011ME-1045

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/11011ME-1045/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 6

Measure 5 DWH Tank Insulation**Components****Inspected**

Comment WRAP DWN TANK OUTSIDE DOOR INSULATE WALL AND BACK OF TUB
WHILE IT IS OPEN REPAIR DOOR (REF-TWFG-PG-35-36)

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DWH Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 6 DWH Pipe Insulation****Components****Inspected**

Comment WRAP DWH WATER PIPES 6' (REF-TWFG-PG37)

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DWH Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 11011ME-1045

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/11011ME-1045/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 6

Measure 7 BELLY REPAIR**Components****Inspected****Comment** REPAIR APPROX 25 SQFT OF BELLY BOARD THAT TORN DOWN.☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	BELLY WRAP REPAIR	SqFt	25	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 8 CO Monitor is Needed****Components****Inspected****Comment** INSTALL 1CO DETECTOR☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO MONITOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 11011ME-1045

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/11011ME-1045/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 5 of 6

Measure 9 Install Kitchen Exhaust Fan**Components****Inspected**

Comment INSTALL NEW VENT FAN IN KITCEN REMOVE OLD ONE VENT TO
OUTSIDE THERE IS A CABNET ABOVE UNIT 30" FAN (REF TWFG-PG-288)

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Kitchen exhaust fan	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 11011ME-1045

Alt. Client ID:

Work Order (Bid Form)

Work Order Name: WO/11011ME-1045/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 6 of 6